Subject: Re: RSS 2.8.0 - Com Port for ICOM conflict
From: Jim Sky <radiosky@radiosky.com>
Date: 02/18/2016 18:00
To: Richard Flagg <rf@hawaii.rr.com>, Wes Greenman <jupgazer@windstream.net>, Francisco Reyes <reyes@astro.ufl.edu>, Baptiste Cecconi <baptiste.cecconi@obspm.fr>, "Whitham D. Reeve" <whit@reeve.com>, Dave Typinski <davetyp@typnet.net>, Jim Brown <starmanjb@gmail.com>, Andrew Mount <capeorion@gmail.com>, Jim Thieman <james.r.thieman@nasa.gov>, Chuck Higgins <chiggins@mtsu.edu>, "Fung, Shing F. (GSFC-6730)" <shing.f.fung@nasa.gov>, Thomas Ashcraft <ashcraft@heliotown.com>

2.8.0 Application Note

If you get a message informing you of a conflict in the com ports, it should be followed by a prompt for a new com port for the ICOM radio. If you do not have an ICOM attached just make up a com port number that is different from your FSX com port. I believe Jim Brown is the only one with a ICOM receiver attached to his RSS. This feature is there for Click and Tune To usage so that you can listen to the signal at some given frequency on the spectrogram. Jim was using this to capture audio from N bursts. We used to use it at WCCRO as a general feature so you could listen to signals remotely. It will work with the R-75 or R8500.

Jim S

On 2/18/2016 12:12 PM, Richard Flagg wrote:

> I get the folowing when I try to start 2.8 - see attached
>
>> ----- Original Message -----
>> **From:** Jim Sky
>> **To:** Richard Flagg ; Wes Greenman ; Francisco Reyes ; Baptiste Cecconi ; Whitham D. Reeve ; Dave Typinski ; Jim Brown ; Andrew Mount ; Jim Thieman ; Chuck Higgins ; Fung, Shing F. (GSFC-6730) ; Thomas Ashcraft
>> **Sent:** Thursday, February 18, 2016 11:17 AM
>> **Subject:** RSS 2.8.0
>>
>> I have been working hard on this update, and now I hope at least a few brave souls will try it out. This fixes numerous issues, but most importantly makes important changes in the use of the atomic clock for timing, and in the seeding and use of correction files. All correction file functions are now under Options/Correction Files. The startup delay and com port conflict are fixed.
>>
>> http://radiosky.com/spec/Spectrograph_Update_2_8_0.exe
>>
>> Thanks and Aloha,
>> Jim S
>>
>> --
>> Jim Sky
>> http://radiosky.com