

This turned out to be in error (31 Oct 2013).
 The Ant1 binding posts were mis-marked;
 they produce a 180 deg phase shift at the
 balun output. As such, the binding post
 marked "1B" is actually the *positive* post.

